

Everything for repairs!

Anti-roll bar kits with mounts and connecting rods

Road debris, road salt and other external factors are frequent causes of damage to the anti-roll bar's coating (see Fig. 1). The worn coating of the anti-roll bar often gives rise to squeaking noises.

Fig. 1



Attention!

When the anti roll paint protection is damaged around the mounting points, always replace the anti-roll bar along with the rubber mounts.



For this reason, febi bilstein offers the anti-roll bar kit, e.g. for VW Golf IV febi no. 36630 (see Fig. 2), which includes not only the fitting kit but also the anti-roll bar. This combination enables a professional repair and avoids complaints. This will save time and money for both the workshop and their customer!

Fig. 2 Anti-roll bar kit with mounts and connecting rods febi no. 36630



Your febi advisor will be pleased to tell you about other anti-roll bar kits!

Simply ask for spare parts by febi bilstein.
The complete range can be found at: www.febi.com