

Important instructions on the replacement of the water pump kits 8MP 376 809-881 and 8MP 376 810-891

AUDI / VW 2.5 TDI V6

If the tensioner (see pictures) 9XU 376 818-511 is not mounted correctly, it may drag on the tensioner pulley 9XU 376 819-661, which can lead to the deterioration of these components, through to a consequential engine damage.



Important instructions on the replacement of the water pump kits 8MP 376 809-881 and 8MP 376 810-891

AUDI / VW 2.5 TDI V6

During installation, ensure the correct positioning of the tensioner lever. As shown in the picture, only the intended area of contact on the tee peg rest. Only then is a sufficient distance between the components ensured and damage can be avoided.



Caution: Be sure to observe the vehicle manufacturer's installation instructions and install only by qualified personnel.