

Technical Bulletin

Kia Sedona Clutch Kit Replacement

Applicable References: ADG03035 / ADG03058 / ADG03325

Applications: Kia Sedona 2.9DT 1999>2006

Date Issued: 11/2012

We have had reports of clearance and gear selection problems for the Kia Sedona 1999>2006 2.9DT. Repairers understandably assume that the clutch is at fault and fit a new clutch kit; however this does not always rectify the problem.

ADG03325



We have found that the cause of the problem can lie with a crack in the clutch release fork, as the release fork on this model can fracture and flex during operation and not allow the clutch to fully disengage.

It is highly recommended that the clutch release fork is replaced during the clutch replacement process. Failure to change the fork could cause clearance problems and difficulty in selecting gears. This would not be covered under the Blue Print warranty agreement.



Cracked fork



www.blue-print.com

Blue Print is a bilstein group brand

Disclaimer : Any technical tips are produced in good faith. Ferdinand Bilstein UK Ltd. always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Ferdinand Bilstein UK Ltd. and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical tips. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.